ANTARES CHARTS CORRECTIONS AND CAUTIONS 2026

Our current set of charts is **Antares Charts 2026:** the following **Corrections** and **Cautions** relate to issues identified after its publication. Corrections will be reflected in our next set of charts, expected to be published in January 2027. All Corrections and Cautions are subject to the Conditions posted on this website.

The UKHO is informed of our findings where appropriate.

NB The 2025 and all earlier chart sets have been superseded by the 2026 set and we strongly recommend that only the current set should be used.

NB Hydrographic surveying and cartography are not precise sciences. There will be errors and misleading representations on our charts as well as those published by others. Please read the sections on our website: 'Making the charts', 'Using the charts' and the 'Conditions'. Take great care at all times but especially if away from the routes described by the sailing directions.

Issues relating to charts in the 2026 set:

Correction: AC 5724A Lochcarron Bay, Loch Carron. Lochcarron Moorings Association (LCMA) has laid four moorings for visitors to access local facilities. One is close to shore (off the 'Post marking large reef' shown on our chart) where shops, cafes, restaurants, bars and fuel are available, with three closer to Slumbay Island, offering shelter from W and SW. Visitors are asked not to remain on the single mooring for more than two hours between 8.00 and 18.00hrs. The LCMA does not recommend the anchor locations shown on our chart as there is said to be a risk of fouling old mooring chains (if you do anchor use a stout tripping line). Boatyard and repair services available at nearby Kishorn Port. Slipway available by appointment. Mini bus service to station two miles away. Overnight mooring on first-come-first-served basis at £15/night payable by BACS – details on floats. LCMA: 07485 732590 or lochcarron.moorings@btinternet.com

Correction: AC 5647A Loch Moidart South Channel. There is a small drying reef close inshore that is not shown. It is unlikely to be a problem unless going ashore by dinghy. It is at the W end of the deep water anchorage in the far NW of our chart. Position 56deg 47.45'N 005deg 52.96'W. A revised chart will be published in 2027.

Correction: AC 5711A Loch Scavaig. There is a very small isolated boulder estimated at 0.5m depth that is just outside the 1m contour. It is in the NE of the bay on the extreme E side of our chart, c. 50m N or the 1.6m sounding, roughly half way between the 1.6m sounding and the drying contour. Position 57deg 11.718'N 006deg 9.049'W.A revised chart will be published in 2027.

Correction: AC 5621D CaolasAnnraidh, Sound of Iona We received a report of an unmarked rock of less than 1m depth to the NE of the channel. as shown in red on the chart below. We have since confirmed its presence (0.8m) and will publish an updated chart in 2027.

ANTARES CHARTS CORRECTIONS AND CAUTIONS 2026



Correction: AC 5624C NE Anchorage, Loch Spelve. We received a report of an uncharted shoal area close to the LW line to the N of our chart. We have confirmed that there is an area of 0.1m just outside our 1m contour as indicated by the red flag on the chart below. An updated chart will be published in 2027



Issues arising from 2026 surveys and reports, to be published as new charts in 2027 *(unless otherwise stated)**:***

None as yet.